CEM120 DEC Belt Tension Adjustment

Rotate the mount in RA to expose the DEC motor cover under the DEC saddle. There are 4 hex head screws hold it in place. Remove them to remove the motor cover.

Slightly release 4 screws that hold the motor on worm assembly. To tighten the belt, push the motor outward. Hold the motor while tightening the screws. Check the mount performance before put the cover on.